



# What Would Good Have Looked Like 41 Truck turning area

ExxonMobil

## What Happened?

Due to the position of the last slurry filled tank to be removed, we needed to change the turning area being used by the trucks coming onto the site to take concrete away . So another area was discussed on site where the trucks were to drive in and reverse to the excavator to be loaded. But when the SPSA was done it was clear that the area was not suitable because there was soil on the ground and objects in the way.



### What's the Worst Thing That Could Happen?

- The truck could hit objects that are in the way
- The soil could get on the tyres and carry onto the main road
- Truck could get a puncture



The trucks were put on temporary stop while the area was cleaned and made safe for traffic

ALL walkways should be kept clear of objects that could hinder access and the soil swept up to avoid transferring off site

Assess

Analyze

Act